MATERIAL SAFETY DATA SHEET

PRODUCT NAME	CAS#
Helium	7440-59-7
TRADE NAME AND SYNONYMS	DOT I.D. NO.
Helium; Helium, Compressed	UN 1046
CHEMICAL NAME AND SYNONYMS	DOT HAZARD CLASS
Helium	Division 2.2
	FORMULA
ISSUE DATE AND REVISIONS	Не
Revised June 2007	CHEMICAL FAMILY
	Inert Gas

HEALTH HAZARD DATA

TIME WEIGHTED AVERAGE EXPOSURE LIMIT

Helium is defined as a simple asphyxiant. Oxygen levels should be maintained at greater than 18 molar percent at normal atmospheric pressure which is equivalent to a partial pressure of 135 mm Hg (ACGIH 1990-1991). OSHA 1989 does not list a TWA for helium.

SYMPTOMS OF EXPOSURE

Effects of exposure to high concentrations so as to displace the oxygen in the air necessary for life are headache, dizziness, labored breathing and eventual unconsciousness. Breathing mixtures of helium with adequate oxygen to support life modifies the voice sound so that it is higher "pitched."

TOXICOLOGICAL PROPERTIES

Helium is nontoxic but the liberation of a large amount in a confined area could displace the amount of oxygen in air necessary to support life.

Helium is not listed in the IARC, NTP or by OSHA as a carcinogen or potential carcinogen.

Persons in ill health where such illness would be aggravated by exposure to Helium should not be allowed to work with or handle this product.

RECOMMENDED FIRST AID TREATMENT

PROMPT MEDICAL ATTENTION IS MANDATORY IN ALL CASES OF OVEREXPOSURE TO HELIUM. RESCUE PERSONNEL SHOULD BE EQUIPPED WITH SELF-CONTAINED BREATHING APPARATUS.

<u>Inhalation</u>: Conscious persons should be assisted to an uncontaminated area and inhale fresh air. Quick removal from the contaminated area is most important. Unconscious persons should be moved to an uncontaminated area, given assisted respiration and supplemental oxygen. Further treatment should be symptomatic and supportive.

Helium

Page 2

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES

PHYSICAL DATA

BOILING POINT	LIQUID DENSITY AT BOILING POINT		
-452.1°F	125 kg/m ³		
VAPOR PRESSURE @ 70 °F	GAS DENSITY AT 70 °F, 1 atm		
Above the critical temp. of –450.3 °F	0.1650 kg/m^3		
SOLUBILITY IN WATER	FREEZING POINT		
Negligible	-456.5°F		
EVAPORATION RATE	SPECIFIC GRAVITY (AIR=1)		
N/A	0.138 @ 70°F		
APPEARANCE AND ODOR			
Colorless, odorless gas			

FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used)	AUTO IGNITION TEMPERATURE	FLAMMABLE LIMITS % BY VOLUME		
N/A	N/A	lel N/A uel N/A		
EXTINGUISHING MEDIA		ELECTRICAL CLASSIFICATION		
Nonflammable, inert gas		Nonhazardous		
SPECIAL FIRE FIGHTING PROCEDURES				
N/A				
UNUSUAL FIRE AND EXPLOSION HAZARDS				
	N/A			

REACTIVITY DATA

STABILITY	-	CONDITIONS TO AVOID		
Unstable				
Stable	Х	N/A		
INCOMPATIBILITY (Materials to avoid)				
None				
HAZARDOUS DECOMPOSITION PRODUCTS				
None				
HAZARDOUS POLYMERIZA	TION	CONDITIONS TO AVOID		
May Occur				
Will Not Occur	Х	N/A		

SPECIAL PROTECTION INFORMATION

RESPIRTORY PROTECTION (Specify type)				
Positive pressure air line with mask or self-contained breathing apparatus should be available for				
emergency use.				
VENTILATION	SPECIAL			
See Local Exhaust	N/A			
MECHANICAL (Gen.)	OTHER			
N/A	N/A			
LOCAL EXHAUST				
To prevent accumulation of high concentrations so as to reduce the oxygen level in the air to less				
than 18 molar percent.				
PROTECTIVE GLOVES				
Any material	EYE PROTECTION			
	Safety goggles or glasses			
OTHER PROTECTIVE EQUIPMENT				
Safety shoes				

SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Evacuate all personnel from affected area. Use appropriate protective equipment. If leak is in container or container valve, contact HSG for special advice.

WASTE DISPOSAL METHOD

Do not attempt to dispose of waste or unused quantities. Return in the shipping container properly labeled, with any valve outlet plugs or caps secured and valve protection cap in place to your supplier. For emergency disposal assistance, contact HSG for special advice.

SPECIAL PRECAUTIONS*

SPECIAL LABELING INFORMATION

DOT Shipping Name: Helium, Compressed DOT Shipping Label: Nonflammable Gas SPECIAL HANDLING RECOMMENDATIONS DOT Hazard Class: Division 2.2 I.D. No.: UN 1046

Use only in well-ventilated areas. Valve protection caps must remain in place unless container is secured with valve outlet piped to use point. Do not drag, slide or roll cylinders. Use a suitable hand truck for cylinder movement. Use a pressure reducing regulator when connecting cylinder to lower pressure (<3,000 psig) piping or systems. Do not heat cylinder by any means to increase the discharge rate of product from the cylinder. Use a check valve or trap in the discharge line to prevent hazardous back flow into the cylinder.

SPECIAL STORAGE RECOMMENDATIONS

Protect cylinders from physical damage. Store in cool, dry, well-ventilated area away from heavily trafficked areas and emergency exits. Do not allow the temperature where cylinders are stored to exceed 125°F. Cylinders should be stored upright and firmly secured to prevent falling or being knocked over. Full and empty cylinders should be segregated. Use a "first in - first out" inventory system to prevent full cylinders being stored for excessive periods of time.

SPECIAL PACKING RECOMMENDATIONS

Helium is noncorrosive and may be used with any common structural material.

OTHER RECOMMENDATIONS OR PRECAUTIONS

Compressed gas cylinders should not be refilled except by qualified producers of compressed gases. Shipment of a compressed gas cylinder which has not been filled by the owner or with his (written) consent is a violation of Law. Always secure cylinders in an upright position before transporting them. NEVER transport cylinders in trunks of vehicles, enclosed vans, truck cabs or in passenger compartments. Transport cylinders secured in open flatbed or in open pick-up type vehicles.

Information contained in this material safety data sheet is offered without charge for use by technically qualified personnel at their discretion and risk. All statements, technical information and recommendations contained herein are based on tests and data which we believe to be reliable, but the accuracy or completeness thereof is not guaranteed no warranty of any kind is made with respect thereto. This information is not intended as a license to operate under or a recommendation to practice or infringe any patent of this Company or others covering any process, composition of matter or use.

Since the Company shall have no control of the use of the product described herein, the Company assumes no liability for loss or damage incurred from the proper or improper use of such product.